



Before Photo: Poor drainage impacts highway, homeowner and vast farmland along County Rd. 48, Groveland, NY
After Photo: Catch basin and underground main installed providing outlet for impounded ground and surface water.

District Update: The Livingston County Soil & Water Conservation District office is now located at the scenic Murray Hill Campus in Mt. Morris. Room 248 Building #1 located in the auditorium wing. Visitors are encouraged to contact the office to schedule an appointment. Ph: 585 489-6274. Email: Robert.Stryker@Livingstoncountynyswcd.gov

For much more information including program and job announcements please be sure to visit the District's new website. <https://livingstoncountynyswcd.gov/>

The District routinely coordinates and then works with local landowners, farmers and municipalities to address environmental concerns. The following photos highlight a project installed this past summer to alleviate drainage concerns alongside a 1,000 foot section of County Rd 48 located in the town of Groveland.

The solution: Installation of two catch basins, 1,300 feet of underground 8" diameter main and 2 natural stone armored stabilized outlets were installed to readily and safely convey ground and storm water drainage downstream.

Results: Erosion, drainage, flooding concerns are addressed. Highway infrastructure, a homeowner's residence and more than 17 acres of prime farmland are significantly improved.

After Photos Below: Locations of 2 stabilized outfalls safely carry and discharge drainage downstream.

